



CAM CARD

4670 Hatchery Road
Waterford, MI 48329
TEL: (248) 674-4967
FAX: (248) 673-7089
www.lsmeng.com
lsmeng@sbcglobal.net

Grind Type: **Grind**
Cam Identification Number: **AX388**
Camshaft Type: **CV8SB-59.C209NL**
Customer: **DARYL WHITMER**

Bearings: **1.999, 1.983, 1.968, 1.952, 1.561**
Fire Order: **1-8-4-3-6-5-7-2**

Installed Timing

0

Intake Lift	<table border="1"><tr><td>380</td></tr></table>	380
380		
Intake Duration	<table border="1"><tr><td>234</td></tr></table>	234
234		
Intake Opens	<table border="1"><tr><td>5 BTDC</td></tr></table>	5 BTDC
5 BTDC		
Intake Closed	<table border="1"><tr><td>49 ABDC</td></tr></table>	49 ABDC
49 ABDC		

Exhaust Lift	<table border="1"><tr><td>380</td></tr></table>	380
380		
Exhaust Duration	<table border="1"><tr><td>238</td></tr></table>	238
238		
Exhaust Opens	<table border="1"><tr><td>51 BBDC</td></tr></table>	51 BBDC
51 BBDC		
Exhaust Closes	<table border="1"><tr><td>7 ATDC</td></tr></table>	7 ATDC
7 ATDC		

LCA	<table border="1"><tr><td>112</td></tr></table>	112
112		
Overlap	<table border="1"><tr><td>12</td></tr></table>	12
12		