

Perfection Tire #36

302 W. Seltice Way
Post Falls, ID 83854

Phone Number: 208-773-2178

Customer:	KENT MOSBY	Date:	8/26/2022 8:43 AM
Company:		VIN	
License No:	73SCAMP	Technician:	DEREK
Odometer:	279	Order No.:	1044889

VEHICLE ALIGNMENT REPORT

PLYMOUTH, 1973, SCAMP

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	5.2°	1.3°	3.8°	2.8°
		Right	4.3°	1.3°	3.8°	3.0°
	Camber	Left	-1.9°	-0.3°	1.3°	0.7°
		Right	-1.6°	-0.3°	1.3°	0.6°
	Toe	Left	-0.05°	0.05°	0.20°	0.15°
		Right	-0.55°	0.05°	0.20°	0.15°
Total		-0.60°	0.15°	0.40°	0.30°	
Rear	Camber	Left	-0.3°	----	----	-0.3°
		Right	-0.2°	----	----	-0.3°
	Toe	Left	-0.15°	----	----	0.00°
		Right	0.15°	----	----	0.10°
		Total	0.00°	----	----	0.10°
	Thrust Angle		0.2°	----	----	0.1°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		7.5°	8.0°	8.0°	4.8°
	Right		7.2°	8.0°	8.0°	4.9°
Included Angle	Left		5.6°	----	----	5.5°
	Right		5.6°	----	----	5.5°
Toe Out On Turns	Left		----	2.0°	2.0°	----
	Right		----	2.0°	2.0°	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		0.3"	----	----	0.1"
	Rear		-0.2"	----	----	-0.3"
Track Width Diff.			2.1"			2.2"
Wheel Base Diff.			0.4"			0.4"
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----